


Photo of Drain Line Flow Control Properly. On Inside.

If Buttons are installed in reverse, Softener Resin will be rinsed out of Tank during Regeneration.




Drain Line Flow Control

Drain Line Flow Control
*Installed CORRECT
Buttons On Inside.



Drain Line Flow Control
*Installed WRONG
Buttons On Inside.



If Drain Line Flow Control is Installed Wrong (Buttons on Outside), Drain Line Flow Control would have O-Ring onto of another O-Ring.

Note: All DCS1 Softeners shipped with Drain Lin Flow Controls installed. If, during installation, Drain Line Flow Control were removed, there is a chance that Drain Line Flow Controls were re-installed backwards. It would be require force to install backwards, and would also result in two O-Rings 'butting' up against each other (See Bottom Photo).